



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 7-12-06 Operator Maria Lopez API #30-0 45-29708
Property Name Trading Post Well No. 1 Location: Unit K Section 30 Township 25 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 48 Intermediate 1/A Casing 280 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/A

REMARKS:

Nothing when opened.

By Steven L. Szuminski

Witness Monica Kuchling

(Position)

E-mail address _____