



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/District.htm>

MECHANICAL INTEGRITY TEST REPORT

(TA or ~~UI~~)

Date of Test 7/24/03 Operator Benson Martin - Greer API # 30-039-06814

Property Name EPCMU Well # 5 Location: Unit A Sec 29 Twn 27 Rge 1E

Land Type:

State _____
Federal _____
Private _____
Indian X

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): Yes

TA Expires: 7/24/08

Casing Pres. _____

Tbg. SI Pres. _____

Max. Inj. Pres. _____

Bradenhead Pres. _____

Tbg. Inj. Pres. _____


Tubing Pres. _____

Int. Casing Pres. _____

Pressured annulus up to 618 psi. for 30 mins. Test passed ~~failed~~

REMARKS:

Pressure dropped ~ 10 psi.




By Ben L. Hoyle
(Operator Representative)

Witness Bence MacDi
(NMOCD)

Pumper
(Position)

REVISED 11-17-98



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000

METER _____ TAKEN OFF _____ M

7/24/63
CHART PUT ON 1.06 P.M.

LOCATION **MIT**
REMARKS **Benson-Martin Green**
EPCMU # 5

APT # 30-039-06814
[Signature]

JUL 2008
RECEIVED
OIL CONS. DIV.
DIST. 8

PRINTED IN U.S.A.