



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://nemnr.state.nm.us/ocd/District III/District.htm](http://nemnr.state.nm.us/ocd/District%20III/District.htm)

MECHANICAL INTEGRITY TEST REPORT

(TA or ~~UE~~)

Date of Test 7-24-03 Operator Benson-Montin-Greer API # 30-039-22593

Property Name EPCMU Well # 41 Location: Unit F Sec 20 Twn 27 Rge 16

Land Type:

State _____
Federal _____
Private _____
Indian X

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____

TA Expires: _____

Casing Pres. _____
Bradenhead Pres. 0
Tubing Pres. _____
Int. Casing Pres. _____


Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 560 psi. for 5 mins. Test ~~passed~~ failed

REMARKS:

Pressured annulus to 600 psi - lost > 10% in 2 min - bleed fluid back to truck & repressured to 560 psi - lost > 10% in 5 min - there was pressure on back side upon arrival - probably packer leak.



By Ben L. Sanchez
(Operator Representative)

Witness Bruce Martin
(NMOCD)

Lumber
(Position)

REVISED 11-17-98

