Submit 3 Copies To Appropriate District	State of New Me	exico	Form C-103	
Office District I	Energy, Minerals and Natural Resources		May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-045-33728	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		STATE FEE E	Z
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	it. Francis Dr., Santa Fe, NM			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreemen	it Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number 4	
1. Type of Well: Oil Well				10 Mg
2. Name of Operator			9. OGRID Number	
McKay Oil & Gas LLC			PECEN	
3. Address of Operator P.O. Box 14738 Albuquerque, NM 87191			10. Pool name of Witdgat ONE Basin Fruitland Coal	
	Basin Fruitland Coal MST.	**************************************		
4. Well Location	2190 fact from the North	line and 1	feet from the West	و کی ک
	feet from the North			
Section 19	Township 29N 11. Elevation (Show whether DR	Range 10W		ounty
5507 GR				
Pit or Below-grade Tank Application □ or Closure □ Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water				
Pit typeDepth to Groundy	· · · · · · · · · · · · · · · · · · ·		ance from nearest surface water	
Pit Liner Thickness: mil			nstruction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	NTENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		SING 🗌
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.□ P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗹	
OTHER:		OTHER:		🗆
	pleted operations. (Clearly state all			
	ork). SEE RULE 1103. For Multip	ole Completions: At	ach wellbore diagram of proposed	completion
or recompletion.				
7/12/06 Nipple up BOP. Pressure	to 500#. Held for 30 min. Driller	l 6 1/4 " hole to 179	9'. Ran 42 JTS 4 1/2 ", J-55, 10.5	# casing
to 1738' KB.				
7/14/06 Comented with 155 SY (3)	10 3 Cu Et) Class R containing 2	4 SK gilsonite W 2	# SK collofisks - Tailed with 110) CV (120 C
7/14/06 Cemented with 155 SX (319.3 Cu. Ft) Class B, containing 2# SK gilsonite W .25# SK celloflake. Tailed with 110 SX (129.8 Cu. Ft) Class B cement W 2% CACL 2 W 1# SK Gilsonite W 1/4 # cello flake. Circulate 15 BBLS cement to pit.				
Report Pt 4/2 Next Report.				
	/~	p-0, p, 1/2	- Next Report.	
I hereby certify that the information	above is true and complete to the h	est of my knowledge	and baliaf I fourther wife that	
grade tank has been/will be constructed or	closed according to NMOCD guidelines], a general permit []	or an (attached) alternative OCD-approve	ed plan .
(1.01 1/2)	Marko -			
SIGNATURE WILL I	TITLE_	Gen. Mgr	DATEDATE	3/06
Type or print name William J. N	Aavhew E-mail addre	SS:	Telephone No. 505-296	6-5508
For State Use Only			- elephone 110. 000-271	2 2200
1/./-10-	ស	EPHTY ON A CAC	III 91	2006
APPROVED BY: A. V. V.	nueva TITLE	OIL O DAS IR	SPECTOR, DIST. BA DATE 2 1	
Conditions of Approval (if any):				