

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-8-06 Ope	rator Blueling on Tes API #30-045-32890
Property Name Meli No	rator Sur ling on GESAPI #30-045-32890 . (005 Location: Unit) Section 9 Township 30 Range (7
	: Tubing 91 Intermediate A Casing 10 Bradenhead 0
	TE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE	FLOW CHARACTERISTICS
Testing Bradenhead INTERM BH Int Csg Int Csg	BRADENHEAD INTERMEDIATE
TIME 5 min	Steady Flow
10 min	Surges
15 min	Down to Nothing
20 min	Nothing Nothing
25 min	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY_	SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS: Jubb When Exercel.	
	AA ~ by
By	Witness / / MULA Luckling
(Position)	
E-mail address $M50$	
E-man address	