



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distic.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-2-06 Operator Burlington Res API #30-0 45-09405
Property Name McCord Well No. 9 Location: Unit B Section 21 Township 30 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 290 Intermediate N/A Casing 306 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			310		
10 min			313		
15 min			315		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges


Down to Nothing

Nothing

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Blew down in 45 seconds

By _____

Witness

Monica Kudlup

(Position)

E-mail address

MSO