submitted in lieu of Form 3160-5 UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Sundry Notices and Reports on Wells Lease Number NMSF-079519A Type of Well 6. If Indian, All. or GAS Tribe Name Unit Agreement Name 2. Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY LP San Juan 28-5 Unit Well Name & Number 3. Address & Phone No. of Operator San Juan 28-5 U #98M PO Box 4289, Farmington, NM 87499 (505) 326-9 API Well No. 30-039-25928 4. Location of Well, Footage, Sec., T, R, M Field and Pool 1720'FSL, 1115'FEL, Sec.13, T-28-N, R-5-W, NMPM Blanco MV/Basin DK 11. County and State Rio Arriba Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandonment Change of Plans Recompletion New Construction Х Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Conversion to Injection Final Abandonment Altering Casing X Other - tubing repair 13. Describe Proposed or Completed Operations 7-2-03 MIRU. Set tbg plug. Encountered H2S. SD for holiday. Conducted H2S training with all personnel. ND WH. NU BOP. SDON. PT tbg to 500 psi, OK. TOOH w/tbg. Recovered 2 bumper springs, 2 brush 7-8-03 type pistons, 1 regular piston, 1 plug and 1 tbg stop from tbg. TIH, blow well & CO to PBTD. TOOH. TIH w/276 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 8653'. (SN @ 8651'). PT tbg to 500 psi, OK. ND BOP. NU WH. RD. Rig released. 14. I hereby certify that the foregoing is true and correct. Signed _ Title Regulatory Supervisor Date 7/9/03 no (This space for Federal or State Office use)