

Scorpion Drilling Company


PO Box 1951

Farmington New Mexico 87499

scorpiondrilling@advantas.net

AP (505) 326-5601

Fax (505) 325-1786



August 5th 2006

Reference:

Merrion Oil & Gas Corporation

Reggae Com #1

Sec. 16, T26N, R11W

San Juan County, New Mexico

API No. 3004533757

A total of six (6) deviation surveys were run using a SURE SHOT tool. These surveys were as follows:

| | |
|------------------|-----------------------------|
| Surface: | 140' = $\frac{3}{4}$ degree |
| Production hole: | 500' = 1 degree |
| | 770' = 1 degree |
| | 1000' = 1 degree |
| | 1500' = 1 degree |
| | 1768' = 1 degree |



These surveys were given to the Merrion Oil & Gas Corporation representative for placement in the well file.

Henry Valdez

President

Scorpion Drilling Company

My Commission Expires February 24, 2010



Physical Address – 1313 W. Murray Drive, Farmington New Mexico, 87401

Henry Valdez (505) 320-5740

Vic Morrow (505) 320-6922

80