



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 8-31-06 Operator Burlington Res API # 30-0 45-20529

Property Name W. McCanyon Well # 1 Location: Unit M Sec 24 Twn 32 Rge 8

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) N

TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. -
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 570 psi. for 30 mins. Test passed/failed

REMARKS:

Pressure rose to 580

Packer set at 3383


tested 3383 to surface

By Ruby Mho
(Operator Representative)

Witness Monica Puchling
(NMOCD)

Consultant
(Position)

Revised 02-11-02



Graphic Controls
Burlington Res.
CHART NO. MC MP-1000-1HR
test #2
METER 3383 to sub 8-31-06
CHART PUT ON 24-32-8
LOCATION W.I. Mead Canyon
REMARKS 30-045-20529

Monica Kuehling

PRINTED IN U.S.A.