NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	el-101.	Operator	Dugan	Productio	n Corp.	ΛDI#	30-045	-24905			
	String	- ;		-					04N		0147
Property Name		P. Dowd			_Location: Unit						9 <u>9</u> 0
Well Status(Sh	ut-In or Producing	Initial PSI:	Tubing_	20	Intermediate		_Casing -	40	Bradeni	nead C	
· · · · · · · · · · · · · · · · · · ·	<u></u>	·			· · · · · · · · · · · · · · · · · · ·					·	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH											
PRESSURE											
	Bradenhead	Interm				FLOW	CHARACT	TERISTICS			
TIME	BH Int Csg	Int Csg	_		<u></u>	BRAD	ENHEAD	INTER	MEDIATE	_	
5 mintues	0 40			Steady Flow	1						
10 minutes				Surges					<u> </u>	-	
15 minutes	0 40		1	Down to No	thing				,	_	
20 minutes			1	Nothing					,	-	
	0 40	, -	7	-	-	X	~			_	
25 minutes	191	<u> </u>	1	Gas					1		
30 minutes		<u> </u>	╛	Gas & Wate	er					_	
				Water					. ۲ ۲۰۰۰ میر		٤.
If bradenhead flowed water, check all of the descriptions that apply below:											
ii bradefinead flowed water, check all of the descriptions that apply below:											
	CLEA	R	FRESH		SALTY	SULFU	JR	BLACK) 	-1. 200g	9 6
		1				_		10	√ - 4		i č
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE									£,		
REMARKS:				• •					The same		. O.
									المرد ا	<u> </u>	
		1								_	
		1								_	
		2								-	
		1	10							_	
Ву	HALL	K X	al		Witne	ss				_	
		Switcher			_					_	
		(Position)			_						