NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

		,		ž												
Date of Test	<u>8/17/06</u> Operator				itor	Dugan	Producti	on Corp.		API#	30-045	-250	50		_	
Property Name		M	1ary A	nne		Well No	3	Location:	Unit	L	Section	9	Township	24	Range	<u>9W</u>
Well Status (Shut-In or Producing) Initial PSI:						Tubing	\$	intermedi	iate		_Casing		<u> 8</u>	Braden	h <u>ead</u>	2
OPEN BRAIL TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes		F lenhea	PRESS				TO ATMOSPHERE Steady Flow Surges Down to Nothing Nothing Gas Gas & Water	FLOW			15 MINUTES TERISTICS INTERME			-		
oo minates	<u>. </u>	!		<u> </u>	 	1	Water								- - 011111	125
If bradenhead flowed water, check all of the descriptions that apply below:															16 18 1	
5 MINUTE S	ТИН		CLEAR		DENHE.	_FRESH	\$	SALTY	INTER	_SULFU		BLAC	K ACA		ECETY COPYS DIST S	96 100 100 100 100
Ву		Ĵ	Jan	Swit (Positi	tcher		3		Witness	S					- - -	