## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 7/27	Operator <u>Duga</u> r	Dugan Production Corp.		30-045-28503			
Property Name Red Ma	ac Well No	. 90 Location:	: Unit B	Section	3 Township		ige <u>12W</u>
Well Status(Shut-In or Producing)	Initial PSI: Tubing	ntermed	liate WA	_Casing		Bradenh <u>ead</u>	<b>つ</b>
OPEN BRADENHEAD AND PRESSU	RE	TO ATMOSPHERI				EÁCH	e ĝin
	nterm			CHARACTE		, DIATE	a <sup>r</sup>
TIME BH Int Csg 5 mintues	Int Csg	Steady Flow	BRADI	ENHEAD	INTERME	DIATE	
10 minutes		Surges					
15 minutes		Down to Nothing		· · · · · · · · · · · · · · · · · · ·		<del></del>	
20 minutes		Nothing					
25 minutes		•					•
		Gas					
30 minutes		Gas & Water	-				
		Water				7	16
If bradenhead flowed wa	ater, check all	of the descriptio	ns that appl	y below:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	M.	6
					<i>\$</i> *	N. Carlotte	70 E
CLEAR_	FRESH	SALTY	SULFU	JRB	LACK .		, ·
	BRADENHEAD		INTERMEDIATI	E		1: <sub>1</sub>	
REMARKS:					- 1	r de late	
<del></del>							
	10 AT 121						
By	9662[[1 <b>4</b> ]		Witness				
	Switcher (Position)						