

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 7/29/06 Operator Dugan Production Corp. API # 30-045-30315  
Property Name Leah Marie Well No 4 Location: Unit O Section 23 Township 26N Range 12W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 5 Intermediate NA Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

	Bradenhead			Interm		
TIME	BH	Int	Csg	Int	Csg	
5 minutes	0		5			
10 minutes	0		5			
15 minutes	0		5			
20 minutes	0		5			
25 minutes	0		5			
30 minutes	0		5			

FLOW CHARACTERISTICS

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**


CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

INTERMEDIATE

REMARKS:



By

[Signature]  
Switcher  
(Position)

Witness

\_\_\_\_\_