## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells		
2003 H	UG 253	Lease Number
Type of Well GAS	P. <b>26</b> 0 E (	NM-111921 If Indian, All. or Tribe Name
Name of Operator	7.	Unit Agreement Name
BURLINGTON RESCURCES OIL & GAS COMPANY LP	<i>;</i>	
Address & Phone No. of Operator	<del></del> 8.	Well Name & Number
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	Negro Canyon #103S API Well No.
		30-045-32937
Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
Unit H, 1395' FNL & 170' FEL, Sec. 2, T31N, R8W, NMPM		Basin Fruitland Coal
	11.	County and State San Juan Co., NM
CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, Type of Submission  Notice of Intent  X Subsequent Report  Plugging Casing Repair Final Abandonment Altering Casing Conversion to Injection		OATA Other - Cavitation
Type of Submission  Notice of Intent Abandonment Type of Action  Notice of Intent Abandonment Type of Action  Notice of Intent Abandonment Type of Action  Notice of Intent Abandonment Type of Action Change of Plans Non-Routine Fracturing Water Shut off Altering Casing Conversion to Injection  Conversion to Injection	X	Other – Cavitation
Type of Submission  Notice of Intent  X Subsequent Report  Casing Repair  Final Abandonment  Altering Casing  Conversion to Injection  Conversion to Injection  Altering Casing  Conversion to Injection  Conversion to Injection  Type of Action  Abandonment  Plugging  Casing Repair  Conversion to Injection  Conversion to Injection  NIRU Aztec #471. LD pump & rods. ND WH, NU BOP. PT-OK. RU to fish liner. tarted energized surges w/air & mist. C/O fill surging & R&R to clean up. 8/2/06 RIH w/iner, had to fish and reset. Liner set @ 5446' w/TOL @ 4879 (41' overlap). POOH. RIH (2) 5034' - 5119'; 5140' - 5162'; 5182' - 5204'; 5243'-5264'; 5341'-5363'. TOH w/mill. To	TOH & Ll jts 5-1/2" k w/plug mill TH w/2-3/8	Other - Cavitation  O liner. Circ. hole to C/O. C-55 15.5# liner. Dropped and m/o perf plugs. Hole ", tbg and landed tbg @
Type of Submission  Notice of Intent  X Subsequent Report  Plugging Casing Repair Casing Repair Mater Shut off Conversion to Injection  3. Describe Proposed or Completed Operations  Altering Casing & R&R to clean up. 8/2/06 RIH w/ inter, had to fish and reset. Liner set @ 5446' w/TOL @ 4879 (41' overlap). POOH. RIH of Side o	TOH & LI jts 5-1/2" k w/plug mill TH w/2-3/8 T – OK. R	Other - Cavitation  D liner. Circ. hole to C/O.  3-55 15.5# liner. Dropped and m/o perf plugs. Hole  ", tbg and landed tbg @  D & released rig 8/10/06.
Notice of Intent X Subsequent Report Plugging Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection  3. Describe Proposed or Completed Operations  1/1/06 MIRU Aztec #471. LD pump & rods. ND WH, NU BOP. PT-OK. RU to fish liner. tarted energized surges w/air & mist. C/O fill surging & R&R to clean up. 8/2/06 RIH w/iner, had to fish and reset. Liner set @ 5446' w/TOL @ 4879 (41' overlap). POOH. RIH 9/2/05/05/05/05/05/05/05/05/05/05/05/05/05/	TOH & Ll jts 5-1/2" k w/plug mill TH w/2-3/8 T - OK. R	Other - Cavitation  D liner. Circ. hole to C/O. 5-55 15.5# liner. Dropped and m/o perf plugs. Hole  ", tbg and landed tbg @ D & released rig 8/10/06.

