



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 8-1-06 Operator Burlington API #30-0 45-26030  
Property Name McCord Well No. 1E Location: Unit F Section 23 Township 30<sup>N</sup> Range 13W  
Well Status (Shut-In or Producing) Tubing 187 Intermediate      Casing 187 Bradenhead 21

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes			<u>187</u>	Steady Flow	
10 minutes			<u>187</u>	Surges	
15 minutes			<u>187</u>	Down to Nothing <u>X</u> <u>TSTM</u>	
20 minutes			<u>187</u>	Nothing	
25 minutes			<u>187</u>	Gas <u>X</u>	
30 minutes			<u>187</u>	Gas & Water	
				Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN BRADENHEAD 20 INTERMEDIATE     

REMARKS: BH blew down in 12 sec. To TSTM.

By Chris Huff Witness     

(Position)

E-mail address     

