



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

9/27/06

Operator

KUKUI - ~~WATSH~~

API #

3004528230

Property Name

ANGEL PEAK 94K18

Location: Unit

Section 9

Township 127N

Range R10W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

2

Intermediate

—

Casing

12

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	12	1				
10 minutes	0	12	1				
15 minutes	0	12	1				
20 minutes	0	12	1				
25 minutes	0	12	1				
30 minutes	0	12	1				
5 minute SI	0	12	1				
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear

Fresh

Salty

Sulfur

Black

5 Minute Shut-in

Bradenhead

0

Intermediate

—

REMARKS:

by

LUCKY LASATEA

Witness

PUMPERA

(Position)

