

30-045 30948

Burlington Resources

RECEIVED

DPNO: 83930401 FOREMAN: 331 SWITCHER 382

2003 JAN -2 PM 1:10

WELLNAME: EAST 9M


070 Farmington, NM

LEASE #: NMSF-077652

UNIT: C SECTION: 25 TOWNSHIP 031N RANGE: 012W COUNTY: 045

REVISED DATE 1/2/2003

This site security plan is located at:
Burlington Resources
3401 30th Street
Farmington, NM 87402



Attachment to the Site Facility Diagram - Lease NM
General sealing of valves. Sales by tank gauging

PRODUCTION PHASE: All drain valves and all sales valves are sealed closed.

SALES PHASE: The tank from which sales are being made will be isolated by sealing closed the drain valve, fill valve, and the equalizer valve(s) during sales

DRAINING PHASE: The tank being drained will be isolated by sealing closed the sales valve, fill equalizer valve(s), and the drain valves on the other tanks.

SEALING OF VALVES

Tank S/T1 - S#1.D#1, SEALED SHUT
Tank S/T2 -
Tank S/T3 -
Tank S/T4 -

NMOCD