



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-24-06 Operator BP API # 30-0 45-24248


Property Name Callegos Canyon Well # 307 Location: Unit L Sec 30 Twn 29 Rge 12

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____



Temporarily Abandoned Well (Y/N): _____ TA Expires: MIT. 10-24 2011

Casing Pres. _____
Bradenhead Pres. 0
Tubing Pres. 90
Int. Casing Pres. _____

Tbg. SI Pres. _____ Max. Inj. Pres. 1200 Allowed
Tbg. Inj. Pres. 90 - not injecting

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS:

Good test 5 psi loss in 30 min

No Chuck Murphy Switch - Good seal 1200 psi packer at 2677 perf 2985-3500
1200# max


By Dulbert Jee
(Operator Representative)

Witness Henry Villanueva
(NMOCD)

Well Site Leader
(Position)

Revised 02-11-02

Handwritten mark



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000-150F

METER *Good test*

CHART PUT ON *4:15 PM*

TAKEN OFF *5:20 PM*

LOCATION *Cealcos Canyon 307*

REMARKS *MIT.*

Written by
Henry Dittmann
Number *D*

30-045-24248
Sec 30-29N 12W

PRINTED IN U.S.A.