RCVD OCT30'06 OIL CONS. DIV. DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-12-06	Operator M&G Drilling Company			API #30-0 45-07153	
Property Name	KRAUSE	Well No.	11 Location: Unit	K Section	28 Township	28N Range 11W
Well Status (Shut-l	In or Producing)	Tubing //O	Intermediate	Casing	13 Bradenhead	<u> </u>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		13	Steady Flow		0	
10 minutes		<u>13</u>	Surges			
15 minutes		<u> </u>	Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas			· · · · · · · · · · · · · · · · · · ·
30 minutes	(.		Gas & Water			
			Water			
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS:						
Ву	OAVIDRON	OFRATOR WI	tness			
	(Position	a)				