RCVD OCT30°06 OIL CONS. DIV. DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-2-06	Operator M&G Drilli	ng Company	API #30-0	45-22289	
Property Name	KRAUSE	Well No.	61 Location: Unit J	Section 28	Township	28N Range 11W
Well Status (Shut-I	n or (roducing)	Tubing 26	Intermediate	Casing 67	Bradenhead	0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		В	RADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		64	Steady Flow		<u> </u>	
10 minutes		64	Surges			
15 minutes		64	Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas		,	
30 minutes			Gas & Water		<u></u>	
			Water		· · · · · · · · · · · · · · · · · · ·	
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS:						
		<u> </u>				
Ву	JAVID RO	ARIC	Witness			
LEASE OPERATOR						
	(Positio	on)				