RCVD DCT30'06 DIL CONS. DIV.

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-29-06 Operator M&G Drilling Company			API #30-0 45-22759		
Property Name	HAMMON	D Well No	47R Location: Unit	L Section	35 Township	27N Range 8W
Well Status (Shut-	In or Producing)	Tubing 15	Intermediate	NH Casing	160 Bradenhead	0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		160	Steady Flow		<u>+</u>	
10 minutes			Surges			
15 minutes			Down to Nothing			
20 minutes			Nothing			
25 minutes	***************************************		Gas			
30 minutes			Gas & Water			
	•		Water			
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
FLowing at time of test						
Ву	bay Rollma Witcher	<u>ر گُرگ</u> ر	Vitness			
(Position)						