RCVD OCT30'06 OIL CONS. DIV.

DIST. 3

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC , NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-17-06	Operator M&G Drilling Co.	mpany	API #30-0	45-22859	
Property Name	KRAUSE	Well No65	Location: UnitC	Section 33	Township	28N Range 11W
Well Status (Shut-I	n or Producing)	Tubing /	Intermediate	Casing	Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		1	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow			
10 minutes			Surges			
15 minutes			Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas			
30 minutes			Gas & Water			
			Water			
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS: SEE ATTACHED DIAGRAM						
By DAVIDROPK Witness LEASE OPERATOR						
(Position)						

M&G DRILLING COMPANY, INC. KRAUSE #65 LEASE NO. NMSF 078863 C SEC. 33: T28N-R11W SAN JUAN COUNTY, NM

SPUD: 1/04/78

1ST DELIVERY: 7/11/78

