ICUD OCT30'0 JIL CONS. DIU

DIST.

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	912.06	OG Operator M&G Drilling Company			API #30-0		45-23198			·
Property Name	KRAUSE	Well No.	11A Location: Unit	K	Section	28	_Township	28N	_Range _	11W
Well Status (Shut-I	n or Producing)	Tubing /	20 Intermediate	P	_Casing	120	Bradenhead	0		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH										
TIME	PRESSURES: INTERMEDIATE	CASING				BR	ADENHEAD FLOWED	INTER	MEDIATE FLOW	ED
5 minutes		170	Steady Flow				0			
10 minutes	/	170	Surges					-		
15 minutes		170	Down to Nothing	;				_		
20 minutes			Nothing							
25 minutes			Gas					-		
30 minutes			Gas & Water			<u> </u>				
			Water							
If bradenhead flowed water, check all of the descriptions that apply below:										
CLEAR FRESH SALTY SULFUR BLACK										
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE										
REMARKS:										
****	Nagiala	as dis der								
Ву	LEASE OPE	ERATOR	Witness					·		
ئىيى.	(Positio	on)	_							