RCVD OCT30'06 OIL CONS. DIV.

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505) 334-6178 FAX: (505) 334-6170

http:\\emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-21-06	Operator M&G Drill	ling Company	API #30-0 45-23626	
Property Name	MARRON	Weli No.	95 Location: Unit K	Section 23 Township	27N Range 8W
Well Status (Shut-	-In or Producing)	Tubing \	Intermediate	Casing <u>29</u> Bradenhead	<u> </u>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		29	Steady Flow	-0	
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		
25 minutes	-		Gas		
30 minutes	-	,	Gas & Water		
	•		Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS:					
ву <u>С</u>	rany Riolinas	<u>m</u>	Witness		
(Position)					