



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

RCVD NOV 6 06

OIL CONS. DIV.

DISP 3
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

9/13/06

Operator

KUKU

API #

3004527827

Property Name

ANGEL PEAK 162#11

(Well Name and Number)

Location: Unit

F

Section

16

Township

T27N

Range

R10W

Pressure (Shut-in or Producing)

Tubing

5

Intermediate

—

Casing

8

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	8					
10 minutes	0	8					
15 minutes	0	8					
20 minutes	0	8					
25 minutes	0	8					
30 minutes	0	8					
5 minute SI	0	8					

Steady Flow		
Surges		
Down to Nothing		
No Flow	1	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear

—

Fresh

—

Salty

—

Sulfur

—

Black

—

5 Minute Shut-in

Bradenhead

0

Intermediate

—

REMARKS:

by

LUCY LASA TEA
PUMP

(Position)

Witness
