

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 11-1-06 Operator	Marglex Resources Twc. API #30-0 45-28524
Property Name 6-655 Well No. 3	Location: Unit H Section 8 Township 7278 Range R136
Well Status (Shut-In or Producing) Tubing 50	Intermediate Casing 80 Bradenhead 0
OPEN BRADENHEAD AND INTERMEDIATE T	O ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes	Steady Flow
10 minutes	Surges
15 minutes	Down to Nothing
20 minutes	Nothing O
25 minutes	Gas
30 minutes	
·	Water
If bradenhead flowed water, check all of the description	as that apply below:
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE
REMARKS:	
By Jack Buylony	Witness
By Jack Buylons  Pumper  (Position)	
E-mail address	