



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 11-16-06 Operator ConocoPhillips API # 30-0 39-24807

Property Name San Juan 29 6 1/4 Well # 301 Location: Unit 1 Sec 2 Twn 29 Rge 6

Land Type:

State ☒
Federal ☐
Private ☐
Indian ☐

Well Type:

Water Injection ☐
Salt Water Disposal ☒
Gas Injection ☐
Producing Oil/Gas ☐
Pressure observation ☐

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 21
Tubing Pres. 375
Int. Casing Pres. 0

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 659 psi. for 30 mins. Test passed/failed

REMARKS:


Packer set at 8045- Rose to 662

By Kurt D. Bailey
(Operator Representative)

Witness Monica Tschling
(NMOCD)

Proj: Ops Lead
(Position)

Revised 02-11-02



Willie S. Barty
GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK
CHART NO. MC MP-1000
METER 11/16/06
CHART PUT ON _____ M TAKEN OFF _____ M
LOCATION 29-6# 30154D
REMARKS API# 30-039-2407
Monica Kunkling

PRINTED IN U.S.A.