



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

RCVD DEC 12 '06
OIL CONS. DIV.
DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 12-12-06 Operator Devon Energy Prod API # 30-0 45-28553

Property Name NEBU Middle Mesa Well # 2 Location: Unit M Sec 11 Twn 3 Rge 7

Land Type:

State _____
Federal ☒
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____

Casing Pres. 6
Bradenhead Pres. 6
Tubing Pres. 835
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 565 psi. for 30 mins. Test passed failed

REMARKS:


will call Karen with packer information

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Foreman
(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

30-045-28553
CHART NO. MC MP-100
12-12-06

METER 11-3-7

TAKEN OFF

CHART PUT ON
NEBD

LOCATION

REMARKS

12/12/06

Middle Mesa SWD 2
DEVON ENERGY

REDDEN 1205
OIL CON. DIV.
DIST. 3 11

NOON

1

2

3

4

5

6 PM

7

8

9

10

11

MIDNIGHT

1

2

3

4

5

6 AM