



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD DEC 21 '06  
OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-20-06 Operator Four Corners Exp API #30-0 3924011 000

Property Name Lybrook Well No. 1 Location: Unit      Section 4 Township 23 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 190 Intermediate      Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>200</u>		
10 min	<u>0</u>		<u>200</u>		
15 min	<u>0</u>		<u>200</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD      INTERMEDIATE     

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By \_\_\_\_\_

Witness \_\_\_\_\_

(Position)

E-mail address \_\_\_\_\_