



**NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT**

**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170**

[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

DIST. 3

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12-19-06 Operator Hustington Energy API #30-0 89-29715

Property Name CLU Well No. 777 Location: Unit SUN/E/NE Section 27 Township 24 Range 6

Well Status (~~Shut-In~~ or Producing) Tubing ☒ Intermediate ☐ Casing ☒ Bradenhead ☒

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>2</u>		<u>100</u>	Steady Flow	
10 minutes	<u>0</u>		<u>100</u>	Surges	
15 minutes	<u>0</u>		<u>100</u>	Down to Nothing ☒	
20 minutes	<u>0</u>		<u>100</u>	Nothing	
25 minutes	<u>0</u>		<u>100</u>	Gas	
30 minutes	<u>0</u>		<u>100</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN BRADENHEAD ☒ INTERMEDIATE ☐

REMARKS:

By Steve Lawrence Witness _____

(Position)

E-mail address _____