



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD JAN 10 '07
OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 1-10-07 Operator Robert L. Bayless API #30-0 45-05738
Property Name 100th SW Well No. 1 Location: Unit 4 Section 21 Township 26 Range 18
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Nothing when opened bradenhead and
intermediate

Tubing is on a vacuum

By Albert Hala
Prod Foreman
(Position)

Witness Monica Kuehn

E-mail address _____