RCVD JAN1207 OIL COMS. DIV.



el la de la Marcolli

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3...

BRADENHEAD TEST REPORT

		(3)	iomit 2 ce	opies to above address)	300	04923676
Date of Test_	7-11-	06 (perator_	Four STAR		
Property Name	Me-4.F	Fed H Well	No. IE	Location: UnitS	ection <u>4</u> Towns	ship 28 Range 10
Well Status (S	hut-In or	Producing) Tub	ing /6	Intermediate Casi	ng40 Bradeni	head
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME BRAI		PRESSURES: INTERMEDIATE	CASING	<u>.</u> .	BRADENHEAD FLOWED	INTERMEDIAT
5 minutes				Steady Flow		
10 minutes				Surges		
15 minutes				_ Down to Nothing		
20 minutes				Nothing		
25 minutes				Gas		
30 minutes				Gas & Water		.·
				Water	·	•
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR_	FR	RESH SAL1	TY	SULFUR BLACK_		
5 MINUTE SHUT-IN BRADENHEAD				INTERMEDIATE	_	
REMARKS:						
	10 april		~ ~. ~~~~		——————————————————————————————————————	
			·			
					manufacture of the section of the se	
- 1016i	ane			16.0		
by NOO R	2617-6	<u>"</u>		Witness N. A		
Positions						