RCVD JAN12'07 DIL CONS. DIV. DIST. 3



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

		45 28690
Date of Test $5-31-06$ Operator	FOUR STAR API #30-0 IND	1-149-8465
Property Name Charley Pair Well No. 5	Location: UnitSection/2_Townsl	hip <u>174</u> Range <u>74</u>
Well Status (Shut-In or Producing) Tubing 4/1	Intermediate Casing_2 Bradenh	ead_ <u>()</u>
OPEN BRADENHEAD AND INTERMEDIATE TO	O ATMOSPHERE INDIVIDUALLY FOR 15	MINUTES EACH
TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow	
10 minutes	Surges	
15 minutes	Down to Nothing	
20 minutes	Nothing	
25 minutes	Gas	
30 minutes	Gas & Water	
	Water	
If bradenhead flowed water, check all of the descriptions	that apply below:	
CLEAR FRESH SALTY	SULFURBLACK	
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE	
REMARKS:		
By Tenhon it	Witness	
- July 1 Wa	· · · · · · · · · · · · · · · · · · ·	
(Position)		
F-mail address		