

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Sundry Notices and Reports on Wells

2006 JUN 8 5 PM 2:24

1. Type of Well  
Oil

RECEIVED  
070 FARMINGTON  
Lease Number  
Jicarilla 70 -  
If Indian, All. or  
Tribe Name  
Jicarilla Apache  
Unit Agreement Name

2. Name of Operator  
Chace Oil c/o  
Golden Oil Holding Corporation

3. Address & Phone No. of Operator

2200 Post Oak Blvd., Suite 720, Houston, TX 77027 713-626-1110

Location of Well, Footage, Sec., T, R, M

1935' FSL & 675' FEL, Section 33, T-24-N, R-4-W, Unit I

7. Well Name & Number  
Jicarilla 70 #14

9. API Well No.  
30-039-228185

10. Field and Pool  
S. Lindrith Gallup-Dakota

11. County & State  
Rio Arriba, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other - Production Test

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

Golden Oil worked on this well from May 8<sup>th</sup> through 18<sup>th</sup>. After fishing out the parted tubing, the casing did not test. Casing leak(s) were found from 3774' to 4576'.

Since the well has not produced for several years, Golden Oil plans to do a 180 day economic test to determine if sufficient production can be realized to justify the expense of a major casing repair workover.

If the production level is sub economic, then the well will be promptly plugged and abandoned.

See the attached report for work details.

14. I hereby certify that the foregoing is true and correct.

Signed

William F. Clark

Title

Contractor

Date

June 1, 2006

(This space for Federal or State Office use)

APPROVED BY

Title

Date

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

FARMINGTON

JUN 13 2006

FARMINGTON FIELD OFFICE

# **A-PLUS WELL SERVICE, INC.**

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 \* fax: 505-325-1211

---

Golden Oil Holding Corporation

**Jicarilla 70 #14**

1935' FSL & 675' FEL, Section 33, T-24-N, R-4-W

Rio Arriba County, NM

Lease Number: Jicarilla Contract #70

API #30-039-228195

June 1, 2006

Page 1 of 1

## **Workover Report**

### **Work Summary:**

- 5/8/06 MOL and RU. Pull rods. Hot oil tubing. Pull tubing, found parted at 4424'; heavy corrosion.
- 5/9/06 Tag fish at 4446'. Recovered 15' piece, parted again. Note tubing very, very corroded. Multiple holes. Heavy scale. Heavy scale in casing.
- 5/10/06 Tag fish at 4472'. Jar fish free. TOH and LD 89 joints 2.375" tubing, total 225 joints, from well.
- 5/11/06 Ran scraper, set RBP at 5720. Test casing, leak, 2 bpm at 400#.
- 5/12/06 Isolate casing leak(s) from 3774' to 4576'. Pull RBP. TIH with bit.
- 5/15/06 Circulate well with KCl water. Clean out fill from 7131' to 7335'. Set Loc Set packer at 7184' with on / off tool above.
- 5/16/06 Rods stacked out on paraffin in tubing. Hot oil again. Pull packer, replace rubber.
- 5/17/06 With packer at 7196', hot oil tubing again.
- 5/18/06 Land 226 joints 2.375" tubing at 7196' KB with Loc Set packer at 5590' and SN at 7161'. Ran 170 3/4" rods and 116 - 7/8" rods. Space out rod and hang off.

RD and MOL.