

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT -" for such proposals

2003 AUG 25 AM 10:58

070 Farmington, NM

SUBMIT IN TRIPLICATE

1. Type of Well



Oil Well



Gas Well



Other

2. Name of Operator

Synergy Operating, LLC (agent for Bois d' Arc Offshore, Ltd.)

3. Address and Telephone No.

PO Box 5513

(505) 325-5449

Farmington, NM 87499

OGRID # 163458

4. Location of Well (Footage, Sec, T, R., M, or Survey Description)

Unit Letter A, 250' FNL, 920' FEL, Sec 15, T20N-R05W

BH-Location

151' FNL, 736' FEL, Unit A, Section 15, T20N, R05W - McKinley County, New Mexico

5. Lease Designation and Serial No.

NMNM-99720

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Bois d' Arc Encino 15 # 1

9. API Well No.

30-031-21008

10. Field and Pool, or Exploratory

WC20N05W15A

Undesignated Mesaverde

11. County or Parish, State

McKinley, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION



Notice of Intent



Subsequent Report



Final Abandonment Notice

TYPE OF ACTION



Abandonment



Recompletion



Plugging Back



Casing Repair



Altering Casing



Other



Change of Plans



New Construction



Non-Routine Fracturing



Water Shut-Off



Conversion to Injection



Dispose Water

(Note: Report results of multiple completion on Well
Completion or recompletion Report and Log Form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work.

If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work.

Synergy Operating, LLC proposes to remediate and close the reserve pit on the subject well in the following manner.

- A) Remove current netting over pit.
- B) Remove and haul soil that is oil stained to the Envirotech land farm facility from around the edges of the pit.
- C) Haul additional soils that may be contaminated to this facility.
- D) Obtain soil samples from the sidewalls, and bottom of the pit per NM-070-93-3004, for analysis.
- E) Submit samples to iina' ba' Laboratory for analysis.
- F) Review results of samples with BLM personnel.
- G) Submit a final pit closure plan for approval.
- H) Await approval before proceeding with final closure, utilizing stockpiled soil on location.

Synergy would like to commence with the hauling of soils on Monday, August 25, 2003.

These actions were verbally discussed with Mr. Mike Wade and Mr. Dale Wirth of the FFO-BLM office on 8-21-2003, at the FFO-BLM office.

14. I hereby certify that the foregoing is true and correct.

Signed:

Thomas E. Mullins

Title: Engineering Manager

Date: 08-22-2003

This space for federal or state office use

Approved by:

Title: EP/ROW Team

Date: 8/28/03

Conditions of approval if any