

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

2007 MAY 10 PM 12:13

RECEIVED
BLM
210 FARMINGTON NM

1. Type of Well Oil	5. Lease Number 14-20-603-584
2. Name of Operator Hart Oil & Gas, Inc.	6. If Indian, All. or Tribe Name Navajo Nation
3. Address & Phone No. of Operator P.O. Box 385, Rangely, CO 81648 (970)629-1116	7. Unit Agreement Name
Location of Well, Footage, Sec., T, R, M 2310' FNL & 330' FWL, Section 14, T-32-N, R-18-W,	8. Well Name & Number Navajo C #5
	9. API Well No. 30-045-20251
	10. Field and Pool Mesa Gallup
	11. County & State San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

RCVD MAY 16 '07

OIL CONS. DIV.

DIST. 3

13. Describe Proposed or Completed Operations

This well was plugged and abandoned on April 30, 2007 per the following:

- 4/25/07 MOL. No pressure. Found 4.5" casing not attached to the 7" surface casing. POH and LD 65 - 5/8" rods Strip on 4.5" head. NU BOP, test. TOH and tally 51 joints 2.375" tubing. Run 4.5" wireline gauge ring. Set 4.5" wireline CIBP at 1590'. Weld 7" casing to 4.5"; install 2" outlet. Game and Wildlife SD operations.
- 4/26/07 Open well, no pressure. TIH with 2.375" tubing and tag CIBP at 1590'. Load hole with 25 bbls of water and circulate well clean. Shut down by Federal and Navajo Game and Wildlife, Department of the Interior.
- 4/27/07 Alexis Watts with Ecosphere Environmental Services. Checked location for Mancos Milkvetch plants.
- 4/30/07 Pressure test casing to 800 PSI, held OK. **Plug #1**, with CIBP at 1590', spot 25 sxs Type III cement (33 cf) inside casing from 1590' up to 1229' to isolate the Gallup perforations and cover the Gallup top. TOH and LD all tubing. Perforate 3 holes at 316'. Establish circulation out bradenhead. **Plug #2** mix 54 sxs Type III cement (72 cf) and pump down the 4.5" casing from 319' to surface, circulate good cement out the bradenhead valve. ND BOP. Cut off wellhead. Mix 15 sxs Type III cement and install P&A marker. RD and MOL. Val Uentillie, BLM representative, was on location. Alexis Watts, Ecosphere Environmental Services, was on location 4/27/07 and 4/30/07.

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor to Hart Oil & Gas Date 4/30/07
William F. Clark, Agent

ACCEPTED FOR RECORD

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

MAY 11 2007

CONDITION OF APPROVAL, if any:

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD