



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-16-07 Operator Robert L. Bayless API #30-0 39-20110
Producer LLC
Property Name Rockhouse Well No. 1 Location: Unit E Section 11 Township 24N Range 7W
Canyon
Well Status (Shut-In or Producing) Tubing 50 Intermediate / Casing 55 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>55</u>	Steady Flow	
10 minutes			<u>55</u>	Surges	
15 minutes			<u>55</u>	Down to Nothing	RCVD MAY23'07
20 minutes			<u>55</u>	Nothing <u>X</u>	OIL CONS. DIV.
25 minutes			<u>55</u>	Gas	DIST. 3
30 minutes	<u>0</u>		<u>55</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH / SALTY / SULFUR / BLACK /

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

looked good

By Adrian Lopez
pumper
(Position)

Witness _____

E-mail address _____