

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test_5-/6-07	Operator Robe	th.Bayless	API #30-0 <u>39 -</u>	25374
Property Name Bue Mes	a Well No. 2 L	Producer ocation: Unit D Sec		ship 24N Range 7ú
Well Status (Shut-In or Produ	cing Tubing 50 Inter	mediate Casin	g <u>52</u> Braden	head <u>N/A</u>
OPEN BRADENHEAD AND	INTERMEDIATE TO AT	MOSPHERE INDIVI	DUALLY FOR 1	5 MINUTES EACH
PRESS TIME <u>BRADENHEAD INTE</u>	SURES: ERMEDIATE CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 2	52	Steady Flow		
10 minutes	. 52	Surges		CVD MAY23'07
15 minutes	53		•	OIL CONS. DIV.
20 minutes	53	Nothing		DIST. 3
25 minutes	53	Gas		D131. 0
30 minutes	54	Gas & Water		
If bradenhead flowed water, chec	k all of the descriptions that a	apply below:		•
CLEAR FRESH_	SALTY SU	LFURBLACK_		
5 MINUTE SHUT-IN BRADE	NHEAD INT	ERMEDIATE 1/14	_	
REMARKS: Looked Good	/			
			`	
	· · · · · · · · · · · · · · · · · · ·			
By Mali- Some	Wit	ness		
Pumper (Position)				
(Position)				
E-mail address				•