

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

**RCVD MAY25'07
OIL CONS. DIV.**

Date of Test 5.21.07 Operator Dugan Production Corp. API # 30-039-06032 **DIST. 3**
Property Name Hurt Well No. 3 Location: Unit B Section 14 Township 25N Range 3W
Well Status(Shut-In or Producing) Initial PSI: Tubing 27.2 Intermediate 27.2 Casing 27.2 Bradenhead 1#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Bradenhead						Interm		FLOW CHARACTERISTICS			
TIME	BH	Int	Csg	Int	Csg			BRADENHEAD		INTERMEDIATE	
5 mintues	0		27.3			Steady Flow					
10 minutes	0		27.2			Surges					
15 minutes	0		27.1			Down to Nothing	X				
20 minutes	0		27			Nothing					
25 minutes						Gas	X				
30 minutes						Gas & Water					
						Water					

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0# INTERMEDIATE _____

REMARKS:

whisper of gas Press

By Carl J. Meeks Witness _____
Switcher
(Position)