

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ood/District III/3distric.htm](http://emnr.state.nm.us/ood/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-21-07 Operator Dugan Production Corp API # 30-043-20676
Property Name Ballymaloe Well No. 2 Location: Unit K Section 25 Township 23N Range 7W
Well Status(Shut-In or Producing) Initial PSI: Tubing 110 Intermediate 0 Casing 270 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>270</u>			
10 minutes	<u>0</u>		<u>270</u>			
15 minutes	<u>0</u>		<u>270</u>			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

RCVD JUN1'07
OIL CONS. DIV.

DIST. 3

By Bd Lrie

Witness _____

Switcher

(Position)