NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

	F7 .0 >5							
Date of Test	5-24-01	_Operator	Dugan Production C	Corp	API#	30-043	-20406	.
Property Name	Dome Fede	<u>ral</u> 29-22-6	Well No. 2 Lo	ocation: Unit	<u>K</u>	Section	29 Township	22N Range 6V
Well Status(Sh	ut-In or Producing) Initial PSI:	TubingIn	termediate ()	Casing	<u> 15</u>	_Bradenhead
OPEN BRA	DENHEAD AN		EDIATE TO ATMOSP	HERE INDIV	IDUALI	LY FOR	15 MINUTES	EACH
	Bradenhead Interm				FLOW CHARACTERISTICS			
TIME	BH Int Csg	Int Csg	_		BRADE	NHEAD	INTERME	DIATE
5 mintues	f) 15		Steady Flow				<u> </u>	
10 minutes	0 15		Surges					
	0 15		1	,				
15 minutes			Down to Nothing	9				
20 minutes		 	Nothing				<u>.</u>	
25 minutes		1	Gas					
30 minutes			Gas & Water					
			Water					
lf basalsals			-l11 -64hl	!	4			
If bradenhead flowed water, check all of the descriptions that apply below:								
	CLEA	₹	_FRESHSA	ALTY	SULFUF	₹	BLACK	_
5 MINUTE S	SHUT-IN	BRADENHE	AD	INTERN	MEDIATE			
REMARKS:								
				. , , , , , ,				
		-						
								··-
							RCL	JUN1'07
Ву	Bolly	'e		Witness			OII	_ Cons . Div.
		Switcher						
		(Position)						DIST. 3