

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-22-07 Operator Dugan Production Corp API # 30-043-20506  
Property Name Dome Tesoro 23 Well No. 1 Location: Unit L Section 23 Township 22N Range 7W  
Well Status(Shut-In or Producing) Initial PSI: Tubing Ø Intermediate Ø Casing 22 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	<u>Ø</u>		<u>22</u>			Steady Flow		
10 minutes	<u>Ø</u>		<u>22</u>			Surges		
15 minutes	<u>Ø</u>		<u>22</u>			Down to Nothing		
20 minutes						<u>Nothing</u>		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE \_\_\_\_\_

REMARKS:

RCVD JUN1'07

OIL CONS. DIV.

DIST. 3

By Bollvie  
Switcher  
(Position)

Witness \_\_\_\_\_