

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-22-07 Operator Dugan Production Corp API # 30-043-20515  
Property Name Dome Tesoro 27 Well No. 3 Location: Unit D Section 27 Township 22N Range 7W  
Well Status(Shut-In or Producing) Initial PSI: Tubing ⊕ Intermediate ⊕ Casing 140 Bradenhead ⊕

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			
TIME	BH	Int	Csg	Int	Csg	BRADENHEAD	INTERMEDIATE
5 mintues	⊕		140			Steady Flow	-
10 minutes	⊕		140			Surges	
15 minutes	⊕		140			Down to Nothing	
20 minutes						Nothing	
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD ⊕ INTERMEDIATE \_\_\_\_\_

REMARKS:

RCVD JUN1'07

OIL CONS. DIV.

DIST. 3

By Ballie  
Switcher  
(Position)

Witness \_\_\_\_\_