## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emy/rd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test	<u>\$-25-07</u> Operator		ator <u>D</u>	Dugan Production Corp			_API#	30-043	-043-20940			_	
Property NameLittle Sis			W	ell No. 1	Location	: Unit	K	Section	31 1	Township	23N	Range	6W
Well Status(Shut-In or Producing) Initial PSI:												h <u>ead &amp;</u>	
OPEN BRA	Р	RESSURE		ATE TO A	TMOSPHER	E INDI					EACH	_	_
TIME	Bradenhead Interm  BH Int Csg Int Csg						FLOW CHARACTERISTIC BRADENHEAD IF			NTERMEDIATE			
5 mintues	<del>0</del>	400		Oteral	. Fla	,	DIOLDE	-INITAP	•	TT I E I CIVIL	DIATE	-	
	#	400		Steady		<u> </u>						-	
10 minutes	<del>-</del>	<del>-                                     </del>		Surges		¥						-	
15 minutes	Ð	400	<del>                                     </del>	Down to Nothing								-	
20 minutes			<del>                                     </del>	Nothin	<del>)</del>							-	
25 minutes				Gas								-	
30 minutes				Gas & Water								-	
				Water								-	
<u>If bradenh</u>	nead flow	<u>ed water</u>	, check	all of the	descriptio	ns tha	at appl	y below	<u>/:</u>				
	С	LEAR	FF	ESH	SALTY		SULFU	IR	BLACK_		_		
5 MINUTE S	SHUT-IN	BRAD	DENHEAD	<u>+</u>		INTER	MEDIATE	≣ <u></u>					
				<del></del>				· · · · · · · · · · · · · · · · · · ·		RCV	D JUN:	i'07	
										OIL	CONS.	DIV.	
											DIST.	3	
Ву	DC 8	η Μτώ				Witnes	ss						
•		Swit	cher		<del></del>		<u> </u>			•••		•	
	ion)	<u> </u>											