

#3-30-045-11751

3380

DATA SHEET FOR DEEP GROUND BED CATHODIC PROTECTION WELLS
NORTHWESTERN NEW MEXICOOperator Meridian Oil Inc. Location: Unit A Sec. 15 Twp 32 Rng 12

Name of Well/Wells or Pipeline Serviced _____

Hubbard #3Elevation — Completion Date 8/18/95 Total Depth 391' Land Type PCasing Strings, Sizes, Types & Depths 8/17 Set 98' of 8" PVC Casing.No Gas, Water, or Boulders were Encountered During Casing.If Casing Strings are cemented, show amounts & types used CementedWith 22 Sacks.

If Cement or Bentonite Plugs have been placed, show depths & amounts used

NoneDepths & thickness of water zones with description of water: Fresh, Clear,
Salty, Sulphur, Etc. Hit Fresh Water at 125'.Depths gas encountered: NoneGround bed depth with type & amount of coke breeze used: 391' Depth.Used 95 Sacks of Asbury 218R (4750#)Depths anodes placed: 375', 360', 350', 340', 330', 320', 305', 255', 245', 235', 225', 215', 205', 170', & 140'.Depths vent pipes placed: Surface to 391'.Vent pipe perforations: Bottom 260'.

Remarks: _____

RECEIVED
FEB 1 9 1997OIL CON. DIV.
DIST. 3

If any of the above data is unavailable, please indicate so. Copies of all logs, including Drillers Log, Water Analyses & Well Bore Schematics should be submitted when available. Unplugged abandoned wells are to be included.

Land Type may be shown: F-Federal; I-Indian; S-State; P-Fee.
If Federal or Indian, add Lease Number.

CPS GROUND BED CONSTRUCTION WORKSHEET

5014-W P/L NAME (S) - NUMBER (S) Hubbard #3

Y984 TOTAL VOLTS 11.71 AMPS 27.9 OHMS .420 DATE 8/18/95 NAME JOHN L. MOSS

REMARKS (ADD FOR CONSTRUCTION LOG) Driller Reported Water AT 125'

INSTALLED 391' of 1" PE Vent Pipe WITH THE BOTTOM 260'

Perforated. Core Breeze TO 115'

DEPTH	LOG ANODE	ANODE	DEPTH	LOG ANODE	ANODE	DEPTH	LOG ANODE	ANODE	DEPTH	LOG ANODE	ANODE	
100	3.1		295	2.4		490			685			
105	3.2		300	2.8		495			690			
110	3.0		305	2.6	7	500			695			
115	2.4		310	2.1		505			700			
120	2.4		315	2.3		510			ANODE	DEPTH	NO	FULLY
125	3.2		320	2.4	6	515					CONC	CONC
130	2.8		325	2.7		520			1	375'	2.5	5.9
135	2.6		330	2.7	5	525			2	360'	2.4	5.4
140	2.4	15	335	2.5		530			3	350'	2.5	5.8
145	2.4		340	2.7	4	535			4	340'	2.9	6.5
150	2.0		345	2.7		540			5	330'	2.8	6.5
155	2.1		350	2.4	3	545			6	320'	2.5	6.1
160	2.0		355	2.3		550			7	305'	2.7	6.3
165	2.5		360	2.3	2	555			8	255'	2.8	6.3
170	2.9	14	365	1.9		560			9	245'	3.0	6.8
175	2.4		370	2.3		565			10	235'	2.9	6.7
180	2.4		375	2.5	1	570			11	225'	2.6	6.1
185	2.4		380	2.2		575			12	215'	2.6	6.1
190	2.3		385	2.4		580			13	205'	2.9	6.0
195	2.5		390	T.D	391'	585			14	170'	3.0	6.5
200	2.4		395			590			15	140'	2.6	4.6
205	2.7	13	400			595			16			
210	2.5		405			600			17			
215	2.6	12	410			605			18			
220	2.6		415			610			19			
225	2.7	17	420			615			20			
230	3.1		425			620			21			
235	2.7	10	430			625			22			
240	2.7		435			630			23			
245	2.6	9	440			635			24			
250	2.4		445			640			25			
255	2.7	8	450			645			26			
260	2.5		455			650			27			
265	2.3		460			655			28			
270	2.5		465			660			29			
275	2.5		470			665			30			
280	2.5		475			670						
285	2.4		480			675						
290	2.5		485			680						

DISTRIBUTION - ORIGINAL - permanent CPS FILE

copy - Division Corrosion Supervisor

copy - Region Corrosion Specialist