

DATE:

6/3/96

#1 = 30-045-12028

DATA SHEET FOR DEEP GROUND BED CATHODIC PROTECTION WELLS
NORTHWESTERN NEW MEXICO

Operator Meridian Oil Inc. Location: Unit H Sec. 14 Twp 32 Rng 12

Name of Well/Wells or Pipeline Serviced

CHAMBERLAIN #1

Elevation 6277 Completion Date 6/3/96 Total Depth 357 Land Type P

Casing Strings, Sizes, Types & Depths 5/31 Set 60' of 8" PVC Casing.

NO GAS OR WATER, BUT 2' (28'-30') of Boulders. Were Encountered During Casing.

If Casing Strings are cemented, show amounts & types used Cemented

WITH 15 SACKS.

If Cement or Bentonite Plugs have been placed, show depths & amounts used

NONE

Depths & thickness of water zones with description of water: Fresh, Clear,
Salty, Sulphur, Etc. HIT FRESH WATER AT 80'.

Depths gas encountered: NONE

Ground bed depth with type & amount of coke breeze used: 357' Depth

Used 66 SACKS of Asbury 218R (3300#)

Depths anodes placed: 740', 325', 315', 305', 295', 285', 270', 260', 250', 240', 230', 220', 205', 195', + 185'.

Depths vent pipes placed: SURFACE TO 357.

Vent pipe perforations: BOTTOM 200'.

Remarks:

RECEIVED
FEB 19 1997

OIL CON. DIV.
DIST. 3

If any of the above data is unavailable, please indicate so. Copies of all logs, including Drillers Log, Water Analyses & Well Bore Schematics should be submitted when available. Unplugged abandoned wells are to be included.

Land Type may be shown: F-Federal; I-Indian; S-State; P-Fee.
If Federal or Indian, add Lease Number.

CPS GROUND BED CONSTRUCTION WORKSHEET

CPS# 2925-W P/L NAME(S), NUMBER(S) Chamberlain #1
 NO 2L13 TOTAL VOLTS 11.33 AMPS 29.7 CHMS 381 DATE 6/3/96 NAME JOHN L. MOSS

REMARKS (notes for construction log) Driller Reported Water AT 80'.
 Installed 357' of 1" PE Vent Pipe, WITH THE BOTTOM
 200' Perforated. Core Breeze TO 165'.

DEPTH	LOG	ANODE	DEPTH	LOG	ANODE	DEPTH	LOG	ANODE	DEPTH	LOG	ANODE	
	ANODE	"		ANODE	"		ANODE	"		ANODE	"	
100			295	2.0	- 5	490			685			
105			300	2.3		495			690			
110			305	2.2	4	500			695			
115			310	2.5		505			700			
120			315	2.4	3	510						
125			320	2.6		515						
130	3.0		325	2.6	2	520						
135	2.8		330	2.0		525			1	340'	2.4	5.5
140	2.3		335	2.3		530			2	325'	2.6	5.4
145	2.8		340	2.5	1	535			3	315'	2.5	5.3
150	2.9		345	2.4		540			4	305'	2.2	4.8
155	2.4		350	2.4		545			5	295'	3.1	5.9
160	2.5		355	T.D	357'	550			6	285'	2.4	5.2
165	2.4		360			555			7	270'	2.4	4.9
170	2.6		365			560			8	260'	2.8	5.6
175	2.7		370			565			9	250'	2.5	5.4
180	3.0		375			570			10	240'	2.3	4.9
185	2.8	15	380			575			11	230'	2.5	5.1
190	2.5		385			580			12	220'	2.7	5.4
195	2.4	14	390			585			13	205'	2.6	5.4
200	2.8		395			590			14	195'	2.4	5.0
205	2.4	13	400			595			15	185'	2.6	5.5
210	2.0		405			600			16			
215	2.8		410			605			17			
220	2.8	12	415			610			18			
225	2.5		420			615			19			
230	2.5	11	425			620			20			
235	2.6		430			625			21			
240	2.3	10	435			630			22			
245	2.7		440			635			23			
250	2.6	9	445			640			24			
255	2.7		450			645			25			
260	2.9	8	455			650			26			
265	2.6		460			655			27			
270	2.3	7	465			660			28			
275	2.1		470			665			29			
280	2.6		475			670			30			
285	2.7	6	480			675						
290	3.1		485			680						

DISTRIBUTION - original - reference CPS FILE
 COPY - Division Corrosion Supervisor