
Form 9-881 a (Feb. 1951)



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Santa	77
1000	Santa	P 62

Lease No. 047017-B

Unit SE/4, Sec. 24, T-28N R-11W. N.M.P.M., San Juan Cty., New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING DE TO F W
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING.		SUPPLEMENTARY WELL HISTORY AUG 27 1901
NOTICE OF INTENTION TO ABANDON WELL	X	
		II S GEOLOGIC L S JRVEY
(INDICATE ABOVE BY CHEC	K MARK NAT	TURE OF REPORT, NOTICE, OR OTHER DATA) FARMINGTON, NEW MEXICO
		August 22, , 19 61
Well No. 10-B/ is located 1940 ft.  SE/h, Sec. 24 28N (4 Sec. and Sec. No.) (Twp.)	from {	
	n Juan	
	County or Sul	
The elevation of the derrick floor above s	ea level	is 5859 ft.
		of WORK  AUG 28 1961  reights, and lengths of proposed casing; indicate mudding jobs, comentimportant proposed work)
We Propose To:	nd an other	DIST. 3
2. Cut off $5\frac{1}{2}$ casing at lowest side $5\frac{1}{2}$ stub to 50 ft. above 3. Fill open hole with mud to su	free po 52" st rface p cop of s	D. of 2074 up into $5\frac{1}{2}$ casing at 1549. Sint. Spot cement plug from 50 ft. intub using approx. 35 sacks cement. Sipple.  Surface pipe. Erect regulation marker
I understand that this plan of work must receive app	roval in writi	ing by the Geological Survey before operations may be commenced.
Company Angel Peak Oil Compa	ny	
Address P. O. Box 808		0.000
Farmington, New Mexico		By L. S. Muennink
	(A.),	Title Production Superintendent