NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

	1-	0	, -													
						Dugan I	^o roducti	on Corp		_API#	30-03	9-05379)		_	
Property Name	·	Jic	arilla	Oter)	Well No_	1	Location	. Unit	K	_Section	21	Township	_24N	_ Range	5W
Well Status(Sh	Proc	ducing)) Initi	al PSI:	Tubing _	60	Intermed	dia <u>te</u>		_Casing	6	<u></u>	_ Brader	nh <u>ead</u>	0	
OPEN BRA	Bradenhead IME BH Int C i mintues i minutes i minutes				SSURE Interm		Steady Flow Surges Down to Nothing Gas Gas & Water Water			FLOW CHARAC BRADENHEAD			INTERMEDIATE OF THE PROPERTY			VED 2007: DIV. DIST. 3
If bradenhead flowed water, check all of the descriptions that apply below:																
		C	CLEAR			FRESH _		SALTY		_SULFU	IR	BLACK			989	CV
5 MINUTE S	TUH		,		DENHEA					_	E					
1)o pressure																
Maria															_	
By Modeland Switcher								_	Witness	S				•	_	
				UVVIL												

(Position)