

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX (505)334-6170


<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 10-28-07 Operator Dugan Production Corp. API # 30-039-22894
Property Name Dome Federal 34-24-7 Well No 3 Location Unit H Section 34 Township 24N Range 7W
Well Status(Shut-In or Producing) Initial PSI: Tubing 26 Intermediate N/A Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes								
10 minutes								
15 minutes								
20 minutes								
25 minutes								
30 minutes								

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water


Nothing

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By  Witness _____
Switcher
(Position)