

30-045-07535

Form 9-331a
(Feb. 1961)Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

	0		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. _____

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 3, 1960

Well No. 1 is located 330 ft. from N line and 2310 ft. from E line of sec. 18


NM/A Section 18 (4 Sec. and Sec. No.) 28N (Twp.) 17W (Range) (Meridian)
Wilcox (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5228 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

This well is to be abandoned at 1580 feet. One Sand tested. Filled fresh water. Cement will be spotted above and below zone.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Schulz & Brennan Drilling Co.Address 621 Staley BuildingMichie Falls, TexasBy B. F. SchulzTitle Partner